ARM Manus Research Station Site Visit 0501M Report

Visit Duration: 18 January to 24 January 2005

Manus Island, Papua New Guinea

Safety:	SV-0501M						
Troy Culgan ORG-815, H2Gen repair parts, MPL laser diode module Safety: Major Hazards: Caustic chemicals(KOH), Explosive gas(H2), AC electricity. Hazard Controls:BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV	Site:	Proposed Dates on Site: 18Jan05 - 24Jan05					
Safety: Major Hazards: Caustic chemicals(KOH), Explosive gas(H2), AC electricity. Hazard Controls:BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV	Team Members:	Ship or hand carry prior to SV:					
Major Hazards: Caustic chemicals(KOH), Explosive gas(H2), AC electricity. Hazard Controls:BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV	Troy Culgan	ORG-815, H2Gen repair parts, MPL laser diode module					
Hazard Controls:BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV		Safety:					
Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV		Major Hazards: Caustic chemicals(KOH), Explosive gas(H2), AC electricity.					
Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV		Hazard Controls:BOM Electrolyser Handbook, BM Electrolyzer					
		Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV					

Site Tasks

Priority	System	Date Completed (dd/Month)	Service Time in Hours	Tasks/Assoc Hazards-Controls For each priority item insert new line(row) for each date/time entry
1	H2GEN			Repair H2GEN
		20/01	6	Replaced CB 1 and two fuses ifor saturation transformer.
				Electrolyser was operational for approx 3 hours and has failed
				under test.Fault appears to be heat related as the unit was
				operable after it had cooled.
		21/1	4	Replaced six diodes in diode stack for electrolyser rectifier,
				believe diodes had become heat stressed when unit
				failed.System now operational and have advised Hymson to
	MDI			return to use of electrolyser gas.
2	MPL	20/04	0	Change out laser diode module
		20/01	2	Laser diode module changed out at 0700 utc 20 Jan, operation to
		21/01		be verified by Albert Mendoza.Current set at 1.23 Refrence:Facility Contact WorkSheet (CS-2005-0056)
3	ORG	21/01		Change out ORG
	OKO	20/01	1	ORG changed out at 13:30 local time, Rex will update the SMET
		20/01		file on loggernet when Manus connectivity is stable
		21/01	0.5	Reference:Facility Contact WorkSheet (CS-2005-0055)
4	GENSET	= ., 0 .	0.0	Inspect battery charger unit and replace it if necessary
		21/01	1	Battery Charger appears to operating correctly
5	GENSET			Inspect for oil usage
		21/01	1	Check for oil leaks, no significant leaks found.Photos of genset
				taken and will forward to Hasting Deering Brisbane upon return to
				Darwin
6	GENSET			Perform 250-hour maintenance
7	SAM			Replace laptop battery
		21/01	1	Battery replaced
8	MMCR			Change out antenna heater filters and TWTA desiccant

P		Date		
rio	System	Completed	Service Time	Tasks/Assoc Hazards-Controls
Priority	.,	(dd/Month)	in Hours	For each priority item insert new line(row) for each date/time entry
		22/01	1	Change out antenna heater filters and TWTA desiccant
_				completed
9	MMCR			Perform maintenance checks
		22/01	1	Maintenance checks complete
10	MPL			Change out shutter timer batteries (AA)
11	MPL	20/04		Perform maintenance checks
4.0	1.01.05	23/01	1	Maintenance checks complete
12	MWR	00/04		Perform maintenance checks
4.0	DOWED.	23/01	1	Maintenance checks complete
13	POWER			Check DC power battery connections
		22/01	0.5	Battery connections clean and secure
14	WSI			Perform maintenance checks
				Inclement weather
15	WSI			Change out desiccant in camera housing
				Inclement weather
16	TRK			Apply rust and sieze protection
				Inclement weather
17	TRK			Grease Azimuth & Zenith Worm Gear Drives - Use Aero Shell
				#17
				Inclement weather
18	VAN			Check for rust and dehumidifier operations and draining
		23/01	1	general site inspection all correct
19	ES&H			Check defibrillator, smoke alarms, emergency lights and fire
				extinguishers
		22/01	1	All ES&H equipment checked and correct
20	ES&H			Change out U-Van and balloon barn eye wash
	_	23/01	1	eyewash changed
21	SAT			Check battery connections and antenna connections
		23/01	1	Check and correct
22	SAT			Check charge on Irridium hand held SAT phone
		20/01		Phone charged and operational
23	VOIP			Check operations
		21/01	1	VOIP operations checked
24	SHIPPING			List items to be shipped following visit
		22/01		MPL Laser Diode supply (WD36048)
	FUTURE			List items needed for future visits (spares, etc.)
	NEEDS			
		22/01		Replacement batteries for PA11 Barometer
				Fendall eyewash concentrate
26	AWS	23/01		AWIB to be replaced
			1	AWIB replaced and weather information broadcast restored